

<https://caddikt.com/>

Frequent question, how do I **unhide** a **drawing** in **Solidworks**? If the component is hidden, you can show it again by right-clicking the component in the FeatureManager design tree (not in the **drawing** view) and selecting Show/Hide > Show Component.

Also know, how do you hide all centerlines in **Solidworks** drawing? Select Detailing from the Document Properties tab. Under Auto insert on view creation, select or clear the check box for: Center marks "holes" -part.

1. Hide/Show Items > View Points.
2. View Points. (View toolbar)
3. View > Hide/Show > Points.

How do I delete hidden lines in Solidworks?

Displaying the Model With Hidden Lines Removed To display the model with hidden lines removed, do one of the following: Click Display Style > Hidden Lines Removed (Heads-up View toolbar). Click Hidden Lines Removed (View toolbar). Click View > Display > Hidden Lines Removed.

How do you hide annotations in Solidworks?

Hiding or Showing Annotations Click the annotations that you want to show or hide. When you hide an annotation, it is hidden on the drawing sheet but not removed from the model's database. If you are not using View > Hide/Show > Annotations, you can right-click an annotation and click Hide to hide the annotation.

How do I make dimensions visible in Solidworks?

To re-display the dimensions, right-click the feature or one of its faces, and select Show All Dimensions. To show dimension names, click View > Hide/Show > Dimension Names or Hide/Show Items > View Dimension Names (Heads-up View toolbar).

How do you remove annotations in Solidworks?

Select the annotation. Click the arrowhead handle. Press Delete.

Why is my part invisible in Solidworks?

This is because the folder for the solid body in the feature tree is not visible until there is more than one body in the part.

How do I unhide all components in a Solidworks assembly?

1. Select the component in the Hide/Show Components list and press Delete.

2. Select the component in the FeatureManager design tree.
3. To show all hidden components again, right-click in the list and click Clear Selections.

How do I Unsuppress all in Solidworks?

1. Click Unsuppress on the Features toolbar. (In parts with multiple configurations, applies to only the current configuration.)
2. Click Edit > Unsuppress, then select This Configuration, All Configurations, or Selected Configurations.

How do you show centerlines in SOLIDWORKS drawing?

In a drawing document, click Options > Document Properties > Detailing. Under Auto insert on view creation, select Centerlines. Click OK.

What are centerlines SOLIDWORKS?

Centerlines are annotations that mark circle centers and describe the geometry size on drawings. You can insert centerlines into drawing views automatically or manually. The SOLIDWORKS software avoids duplicate centerlines. If you dimension to a centerline, the extension lines are shortened automatically.

How do I remove a sketch line in SOLIDWORKS?

To delete: Click the line or text and press the Delete key.

How do you unhide annotations in Solidworks?

on the Annotation toolbar, or click View > Hide/Show > Annotations. All annotations are displayed; hidden annotations are in gray. Click the annotations that you want to show or hide.

Can you hide construction lines in Solidworks?

To hide all construction geometry, use the "Shift" and "P" keys simultaneously.

How do you hide a sketch relationship in Solidworks?

How do I toggle the display of sketch relations? (View toolbar) or View > Hide/Show > Sketch Relations to toggle the display of sketch relations. If you clear View > Hide/Show > Sketch Relations, but you select a sketch entity in an open sketch, the sketch relation icons appear.

How do I show hidden edges in Inventor?

1. Right-click the view.
2. Click in the drop-down menu Edit View
3. In the dialog box Drawing View click on the Hidden Line button.
4. If you see this icon. , it means that you have activated the checkbox on Style above the buttons.
5. After clicking the OK button, you should see the hidden lines, in the view(s).

What are object lines?

A visible line, or object line is a thick continuous line, used to outline the visible edges or contours of an object.

Wrap Up:

I believe I covered everything there is to know about Frequent answer: How to unhide text in solidworks drawing? in this article. Please take the time to examine our CAD-Elearning.com site if you have any additional queries about Solidworks software. You will find various Solidworks tutorials. If not, please let me know in the remarks section below or via the contact page.

The article clarifies the following points:

- How do I delete hidden lines in Solidworks?
- How do you hide annotations in Solidworks?
- How do I make dimensions visible in Solidworks?
- How do you remove annotations in Solidworks?
- Why is my part invisible in Solidworks?
- How do I unhide all components in a Solidworks assembly?
- How do I Unsuppress all in Solidworks?
- How do you unhide annotations in Solidworks?
- Can you hide construction lines in Solidworks?
- How do you hide a sketch relationship in Solidworks?