




How to delete stuff in autodesk inventor?

Description

Starting with this article which is the answer to your question How to delete stuff in autodesk inventor?.CAD-Elearning.com has what you want as free Autodesk inventor tutorials, yes, you can learn Autodesk inventor software faster and more efficiently here.

Millions of engineers and designers in tens of thousands of companies use Autodesk inventor. It is one of the most widely used design and engineering programs and is used by many different professions and companies around the world because of its wide range of features and excellent functionality. And here is the answer to your How to delete stuff in autodesk inventor? question, read on.

Introduction

1. In the browser or graphics window, select the work, sketched, or placed feature to **delete**.
2. Right-click and choose Delete.
3. In the Delete Features dialog box, specify which dependent features, sketches, or work features to additionally delete:
4. Click OK.

Also know, how do you **delete** a line in **Autodesk Inventor**?

1. Go to sketch tab.
2. Select Trim.
3. Click on the lines that you want to remove.

Also the question is, how do I delete a shape in Inventor?

Similarly, how do you delete a block in Inventor? To **delete** a title block from the drawing, right-click the title block browser node in the sheet and click Delete.

Subsequently, how do I **delete** all constraints in **Inventor**? Go to browser->right-click on the sketch node->Export sketches as->save it as a DXF file. Delete the sketch geometry in sketch edit

environment. Import the DXF file back to the sketch. All the constraints should be gone.

1. In the browser or graphics window, select the work, sketched, or placed feature to delete.
2. Right-click and choose **Delete**.
3. In the Delete Features dialog box, specify which dependent features, sketches, or work features to additionally delete:
4. Click OK.

How do you delete a dimension in Inventor?

How do I delete a 2D sketch in Inventor?

How do I edit property fields in Inventor?

In the browser, right-click a sketch symbol, border, or the Field Text entry of a title block, and then select Edit Field Text. The dialog box displays automatically when you insert a title block, border, or sketch symbol containing prompted entries in the drawing.

How do I delete a project in MIT App Inventor?

This is the new feature added in MIT APP INVENTOR which allows users not to permanently delete the project once they click the Delete button intentionally or unintentionally. Rather it moves the deleted projects to Trash tab and once user makes up his mind he can go to trash tab and delete the project permanently.

How can you remove a constraint inventor quizlet?

Applied geometric constraints can be removed by selecting the constraint flag and then pressing the Delete key on the keyboard.

How do you get rid of the yellow lines in Inventor?

You can right-click on this Projected Loop browser node and select delete.

What is a collinear constraint?

Constrain the collinearity between two linear objects. If one line is moved, the other constrained line adjusts to remain aligned. The lines do not need to be aligned when you place the constraint; the first line moves to become collinear to the second line.

How do I delete an extrusion in Inventor?

How do you delete all objects in a layer in Autocad?

Select an object on the layer which you want to delete from drawing area and press Enter then select Yes from command line options and press enter again. All objects of the selected layer will be deleted and the layer will also be purged.

How do you delete a layer?

Right-click on the Layers palette, and choose Delete. Drag the layer to the Delete Layer button. 1 On the Layers palette, click the name of the layer you want to clear. Make sure that nothing is selected outside the layer.

How do I delete dimensions?

1. In the Dimension Library (Shared Library or Application pane), right-click a dimension and select Delete Dimension.
2. Click Yes.

How do I edit a sketch in Inventor?

1. Double-click the sketch icon in the browser.
2. Right-click the sketch in the browser and choose Edit Sketch or Edit 3D Sketch.
3. Right-click the sketch plane in the graphics area and choose Edit Sketch or Edit 3D Sketch.

How do you hide sketches in Inventor?

In Inventor, go to view tab, object visibility, and uncheck sketches for 2D and 3D. Hope that's what you're looking for.

How do you remove unwanted lines in AutoCAD?

To resolve the issue, try out the following: Disable Smooth Line Display. On the command line in AutoCAD, type LINESMOOTHING and set it to Off or 0 (zero).

How do I remove model space in AutoCAD?

1. On the Quick Access toolbar, click Project Navigator.
2. Click the Views tab.
3. Select the view drawing that contains the model space view you want to delete, and expand it.

4. Select the model space view to delete, right-click, and click Delete.

Bottom line:

Everything you needed to know about How to delete stuff in autodesk inventor? should now be clear, in my opinion. Please take the time to browse our CAD-Elearning.com site if you have any additional questions about Autodesk inventor software. Several Autodesk inventor tutorials questions can be found there. Please let me know in the comments section below or via the contact page if anything else.

The article clarifies the following points:

- How do you delete a dimension in Inventor?
- How do I delete a 2D sketch in Inventor?
- How do I edit property fields in Inventor?
- How do you get rid of the yellow lines in Inventor?
- What is a collinear constraint?
- How do you delete all objects in a layer in Autocad?
- How do I delete dimensions?
- How do I edit a sketch in Inventor?
- How do you remove unwanted lines in AutoCAD?
- How do I remove model space in AutoCAD?