




How to delete a line in solidworks?

Description

How to delete a line in solidworks? “ The answer is in this article! Finding the right Solidworks tutorials and even more, for free, is not easy on the internet, that’s why our CAD-Elearning.com site was created to offer you the best answers to your questions about Solidworks software. Millions of engineers and designers in tens of thousands of companies use Solidworks. It is one of the most widely used design and engineering programs. It is used by many different professions and companies around the world because of its wide range of features and excellent functionality. And here is the answer to your How to delete a line in solidworks? question, read on.

Introduction

On the ribbon, choose Draw > Construction Line > Erase. On the menu, choose Draw > Construction Line > Erase.

Also, how do u delete a line in Solidworks? To delete: Click the line or text and press the Delete key. To move: Click the line or text and drag to a new location.

Correspondingly, how do you delete something in Solidworks?

1. Select one or more items to delete in the graphics area or in the FeatureManager design tree.
2. Click Delete (Standard toolbar), click Edit > Delete or press Delete.

Quick Answer, how do I delete unnecessary lines in Solidworks?

Beside above, how do I delete part of a sketch in Solidworks? You have to exit the sketch before you can delete it, and the same for the feature. To delete something, right-click on it in the design tree and select “delete.”

How do you delete a line in CAD?

How do I delete a segment in SOLIDWORKS?

1. Open any sketch with segments or closed spline endpoints.
2. Right-click the entity to detach and click Detach Segment on Drag .
3. Drag the endpoint to the desired location.
4. Right-click the entity and clear Detach Segment on Drag.

How do you delete bodies in SOLIDWORKS?

1. Click Delete/Keep Body on the Features toolbar, or click Insert > Features > Delete/Keep Body.
2. In the PropertyManager, select Delete Bodies or Keep Bodies.
3. For Bodies to keep or Bodies to delete, select bodies in the graphics area or from the Solid Bodies folder for Solid/Surface Bodies to Delete/Keep .

How do I delete a fillet in SOLIDWORKS?

Hover over another fillet in the FeatureManager design tree that is applied to multiple edges. You want to remove the fillet from the circular edge only. Select the circular filleted edge. Click Remove.

How do I delete part of a line in Solid edge?

How do you delete a mesh line in SolidWorks?

How do I get rid of the GREY lines in SolidWorks?

1. Click Display Style > Hidden Lines Removed (Heads-up View toolbar).
2. Click Hidden Lines Removed (View toolbar).
3. Click View > Display > Hidden Lines Removed.

How do you hide lines in Solidworks drawing?

1. Click Hide/Show Edges.
2. Select the edges to hide (you can select edges individually, or use box selection), then click .
3. To show edges, click Hide/Show Edges.
4. Select the hidden edges highlighted in orange, (you can select edges individually, or use box selection), then click .

How do you cut an imported part in Solidworks?

How do I remove unwanted lines in Sketchup?

Select the Eraser tool () or press the E key. Tap the Ctrl key (Microsoft Windows) or the Option key (macOS) to toggle Smooth Edges and then "erase" these lines the same way you would to delete them.

How do you delete a construction line in Tekla?

Select the grid line you want to delete. Ensure that you do not have any other objects selected. If you also have other objects selected, Tekla Structures only deletes the objects, not the grid line. Right-click and select Delete from the pop-up menu.

How do I remove a line from a component in Sketchup?

Assuming you've made the cabinets as groups or components, open them for editing and hide the edges you don't want to see. You can use the Eraser tool with Shift to do that.

What is Erase command in CAD?

The erase command is used to remove or delete objects from the drawing, as shown in the below image: Here, 1 and 2 are the numbers of the selected objects. The selected objects can also be removed with the help of the "Delete" button on the keyboard.

How do I delete unwanted lines in AutoCAD?

To resolve the issue, try out the following: Disable Smooth Line Display. On the command line in AutoCAD, type LINESMOOTHING and set it to Off or 0 (zero).

How do I delete part of a line in AutoCAD?

Draw your polyline, rectangle or polygon or whatever. When modifying hold down the CTRL Key (just the segment will highlight) select it and Press the Delete key on the keyboard.

Wrap Up:

I believe I covered everything there is to know about How to delete a line in solidworks? in this article. Please take the time to examine our CAD-Elearning.com site if you have any additional queries about Solidworks software. You will find various Solidworks tutorials. If not, please let me know in the remarks section below or via the contact page.

The article clarifies the following points:

- How do you delete a line in CAD?
- How do I delete a segment in SOLIDWORKS?
- How do you delete bodies in SOLIDWORKS?
- How do I delete a fillet in SOLIDWORKS?
- How do I delete part of a line in Solid edge?
- How do I get rid of the GREY lines in SolidWorks?
- How do you cut an imported part in Solidworks?
- What is Erase command in CAD?
- How do I delete unwanted lines in AutoCAD?
- How do I delete part of a line in AutoCAD?

<https://caddikt.com/>